



HONG KONG
ASIAWORLD-EXPO
亞洲國際博覽館

3RD TO 6TH
DECEMBER
2025



Hong Kong Experience in Control of Wet Pack through Scientific Approach

Name: Teddy LEE (teddy@hkssma.org)


Affiliation: Vice Chairman, HKSSMA



Content

- Introduction
- Common Cause of Wet Pack
- Physic of Steam Sterilization
- Wet Load Strategy
- Management Aspects for Wet Pack Prevention





As at 31 March 2022		Hospital / Institution	Specialist Outpatient Clinic	General Outpatient Clinic
1	Castle Peak Hospital	✓	✓	
2	Pok Oi Hospital +	✓	✓	
3	Siu Lam Hospital	✓		
4	Tin Shui Wai Hospital +	✓	✓	
5	Tuen Mun Hospital +	✓	✓	
6	Tuen Mun Eye Centre		✓	
7	Kam Tin Clinic			✓
8	Madam Yung Fung Shee Health Centre			✓
9	Tin Shui Wai (Tin Yip Road) Community Health Centre			✓
10	Tin Shui Wai Health Centre (Tin Shui Road)			✓
11	Tuen Mun Clinic			✓
12	Tuen Mun Wu Hong Clinic			✓
13	Yan Oi General Out-patient Clinic			✓
14	Yuen Long Jockey Club Health Centre			✓

SSD in Hospital	No of OT	Hospital Bed	Monthly average Instrument Reprocess (per set)	Remarks
Tuen Mun Hospital	22	2100	7100	2 Psy (~1600beds)
Pok Oi Hospital	10	800	4500	
Tin Shui Wai Hospital	4+3	300	2600	3 Remote Theaters + 9 OPDs



A. Introduction

- Wet loads can be defined in different ways **depends on where moisture can be found**
 - If water is present in the load, even if the outer packaging is not wet at the time of inspection, it **could contaminate the packaging** and render it transparent to microbial penetration
- (HTM 01-01, Part C)
- Provide a pathway for microorganism to enter the just sterilized pack
(Threat of wet pack)



B. Common Cause of Wet Pack

1. Excessive moisture content in steam (Wet steam)
2. Mal-function of vacuum pump
3. Mal-function of steam trap
4. Use correct steam traps located and maintained correctly
5. Inadequate insulation of steam pipes
6. Poor packing configuration
7. Over-weight of sterile pack
8. Over-load of sterile pack



B. Common Cause of Wet Pack

9. Improper loading of sterilization cart – condensate drain to the pack at lower level
10. Improper cooling of sterilized load
11. Mixed load
12. Accumulation of condensate on one location inside the pack
13. Inadequate conservation of heat energy for drying
14. Inadequate drying time
15. The temperature for cooling water used in the vacuum pump exceeding 15 °C as recommended by EN 285




C. Physic of steam sterilization



Sterilization cycle


Temp
(°C)

Pressure
(mbar)





Pulsing Stage

Air Removal




Steam Admission



Sterilization

Steam




Steam

Steam

➤ Less than 3.5% of air
(EN285 2015 13.3.1)


Drying

Air, Steam and Condensate



Steam Sterilization Cycle - Failure

- Poor steam quality or air leakage in the sterilizer causing insufficient air removal
- Air can lurk in the center of the package and hinder sterilization



Wet Pack Prevention

Don't remain sterile items in sterilizer for drying



Conservation of Heat Energy for Drying




Plastic bottom have little heat energy to convert condensate to steam



Conservation of Heat Energy for Drying

- During drying phase, the condensate accumulated on the hot metal surface will be vaporized to become steam which expands its volume (1:1694 at 1 bar).



Condensate Vaporized and Expanded Out

Smallest size container

- **Size:** 254mm x 258mm x 75mm
- **Volume** = 4914.9 cm³
- **Condensate change to steam volume ratio** is 1:1690 at 1 bar = 100 °C
- **Assume all condensate vaporized.** 4914.9 cm³ / 1694 = 2.9 cm³ condensate



Physical Properties of Saturated Steam

Absolute pressure	Boiling Point	Specific Volume (steam)	Density (steam)	Specific Enthalpy of Liquid Water(sensible heat)	Specific Enthalpy of Steam(total heat)	Latent heat of Vaporization
(bar)	(°C)	(m ³ /kg)	(kg/m ³)	(kJ/kg)	(kJ/kg)	(kJ/kg)
0.02	17.51	67.006	0.015	73.45	2533.64	2460.19
0.1	45.83	14.675	0.068	191.84	2584.78	2392.94
0.2	60.09	7.65	0.131	251.46	2609.86	2358.4
0.3	69.13	5.229	0.191	289.31	2625.43	2336.13
1 ¹⁾	99.63	1.694	0.59	417.51	2675.43	2257.92
2	120.23	0.885	1.129	504.71	2706.29	2201.59
3	133.54	0.606	1.651	561.44	2724.66	2163.22
3.5	138.87	0.524	1.908	584.28	2731.63	2147.35
5	151.85	0.375	2.669	640.12	2747.54	2107.42

1) = 1 bar abs = 0 bar gauge = 100 kPa abs = atmospheric pressure



Condensate Vaporized and Expanded Out


- **Condensate change to steam volume ratio is 1:7650 at 60°C**
- **Assume all condensate vaporized. $4914.9 \text{ cm}^3 / 7650 = 0.64 \text{ cm}^3$ condensate**
- **At 100 °C with 2.9 cm³ condensate = 97% - 100% relative humidity**
- **At 60°C with 0.64 cm³ condensate = $0.64 / 2.9 = 22\%$ relative humidity. Consideration should be calculated relative humidity of the filter air for balancing the pressure at the end of the sterilization cycle.**

Smallest size container (shown as image)



D. Wet Load Strategy


1) Record and analysis (repack if wet)



Date	Hospital	Sterilizer No.	Cycle	Program	Drying time	Air flush time	Position	Wetload was found	Set Template	Set ID	Weight of set
8/4/2024	TMH	DH15472	3325	3	28:50	19:10	8	爐內	TMH.T10048	TMH.T10048.05	6.9
8/4/2024	TMH	DH15472	3329	3	28:19	19:14	8	爐內	TMH.T20069	TMH.T20069.08	6.79

Record wetload position and parameter

3)Load Dryness Test



$$\Delta m = \frac{(m_2 - m_1)}{m_1} \times 100\%$$

Weight Comparison

EN285



2)Content Organize

A. Change Container



B. Remove low height capacity items



C. Weight Control

≤15KG




D. Minimize graphic tray



D. Wet Load Strategy

4. Optimal Drying Stage

- Extended drying time (e.g. <20min)
- Air Flush after Normal Sterilization Process



6. Use of absorbent liner

- Increase surface area of the condensate and easy to absorb energy
- Hide the wet pack problems

5. Vacuum Pressure Performance

Compare the vacuum pressure for assuring the efficacy of pump



Loggers in process


#19720237

Calibration date 02/11/2023 15:37:21

Overall result


Passed

Detailed results	Normal	Actual
2. Pulsing 1		
✓ Duration	>= 00:04:07 ; <= 00:07:30	00:06:38
✓ Limits (Pressure)	>= 0.00 mbar	107.00 ... 967.00 mbar
3. Pulsing 2		
✓ Duration	>= 00:03:30 ; <= 00:05:23	00:04:54
✓ Limits (Pressure)	>= 0.00 mbar	1117.00 ... 1912.00 mbar
4. Pulsing 3		
✓ Duration	>= 00:00:00	00:01:36
✓ Limits (Pressure)	>= 0.00 mbar	2130.00 ... 2893.00 mbar
5. Steam Admission Stage		
✓ Limits (Temperature)	>= 0.00 °C	122.55 ... 134.66 °C
✓ Duration	>= 00:00:00	00:00:33
✓ Limits (Pressure)	>= 0.00 mbar	2165.00 ... 3093.00 mbar
6. Sterilization Stage		
✓ Limits (Pressure)	>= 3042.00 mbar	3090.00 ... 3149.00 mbar
✓ Limits (Temperature)	>= 134.00 ; <= 137.00 °C	134.51 ... 135.29 °C
✓ Duration	>= 00:03:30	00:03:30
7. Drying Stage		
✓ Limits (Pressure)	>= 0.00 mbar	49.00 ... 76.00 mbar
✓ Duration	>= 00:24:13 ; <= 00:24:50	00:24:36
8. Air Flush Stage		
✓ Duration	>= 00:19:52 ; <= 00:31:13	00:22:49
Total process		
✓ Duration	>= 00:00:00	01:16:30



Dramatically Decrease of Wet pack Occurrence

No. of Wet Pack



E. Management Strategy – 1) Integrating Continuous Staff Training

- Centralize Training Practice
- Reform the training on job functions
- Transfer the practical experience
- Knowledge oriented and skill transfer
- Team building

Reform Weekly Training


Autoclave Operator Training

Review Preceptorship Prog

T&T Prog

Updated Training Contents

Refreshment Training





2) Systematic Incident Documentation

Report by SSD

	NTWC Sterile Services Department	文件號碼: NTWCSSD-C-NM-003-V13
	Quality Improvement on Reporting Nearly Missed Case in NTWC SSD	版本: 13
		生效日期: 01-04-2024
		下次修版: 01-04-2027
		頁數: 頁 1

Quality Improvement on Reporting Nearly Missed Case in NTWC SSD

All Nearly Missed Case should be reported through email within 48 hours.

Severity Grade	Nearly Missed belongs to group 3 & 4 should report to DOM verbally in advance
1. Low risk	Nearly Missed happens within SSD.
2. Moderate risk	Nearly Missed is related to customers and is related to product's non-conformity.
3. Moderate high risk	Nearly Missed is related to expensive instruments / potential complaint.
4. High risk	Nearly Missed may affect patient safety or clinical service.

Non-conforming product

Hospital Code for reporting & statistics	TMH: T	POH: P	TSWH: W
--	--------	--------	---------

Follow up action	TMH	POH	TSWH
Internal training	W C LAW & All PCAI		
Staff interview	Cherry CHAN	Martin TANG	Edward YIP
System review	Leo YEUNG	S M KO	S M KO / Ben LAI
Wet load follow up	Ken YIP	Johnson WAN	Ben LAI

Management review	Frequency
Nearly Missed Case Statistics	Monthly
Review in SSD Management meeting	Quarterly
Nearly Missed Case Review Training	Weekly

IOD / OSH Incident

Immediate action	Duty i/c
Follow up action by Department Safety Officer	
TMH DSO	Cherry CHAN
POH DSO	Priscilla LAW
TSWH DSO	Ben LAI

Non-OT Related

Fault of machine or facility
Shortage of supply
Environmental defect

Immediate action	Duty i/c
Follow up action by SSD i/c	
TMH	Leo YEUNG
POH	S M KO
TSWH	S M KO / Ben LAI

Wet Load

Report by SSD staff:	Record by Wet load form
Report by customers:	Nearly missed report

Author : Chu Yee Man Approved by : Ko Shui Mei
Rank : EOII Rank : WM
Date : 01/04/2024 Date : 01/04/2024

Report by Customers

Wetload_nav

Wetload Record

EditExport to ExcelClose Form

Wetload

Date	Hospital	Sterilizer No	Cycle	Program	Drying time	Air flush time	Position	Wetload was found	Set Template	Set ID	Weight of set
8/4/2024	TMH	DH15472	3325	3	28:50	19:10	8	蓋內	TMH.T10048	TMH.T10048.05	6.9
8/4/2024	TMH	DH15472	3329	3	28:19	19:14	8	蓋內	TMH.T20069	TMH.T20069.08	6.79

記錄14411已轉檔1增息



Nearly Missed Incident Edit Menu

Incident Code: 240913T00302	Incident Date: 13/9/2024 17:35:00	Incident Closed: 13/9/2024 11:44:20
Hospital: TMH	Reported by: [Name]	Follow Up By: [Name]
Category: Non-Conforming product	Latest Update: 13/9/2024 11:44:23	Severity: Moderate risk
Sub-Category: Wet Pack	Updated by: [Name]	Feedback By: OT/ TMEC

Incident Heading* Wet Load observed in TMH.N20051.01 KNEE PROSTALAC(L)(S.O.4)

Characters Left 61

Incident Details* On 12/9/2024 17:35, OT WM inform SSD that water droplet was encountered on one of the L Size of KNEE PROSTALAC in TMH.N20051.01 KNEE PROSTALAC(L)(S.O.4).

Characters Left 1836

Root Cause Owing to material of instrument, the absorbed heat capacity was not sufficient to vaporize the condensate after sterilization. The loading configuration could not facilitate the drainage of condensate.

Characters Left 798

Immediate Action SSD I/C was informed. The problematic instrument was not used in operation. OT performed usage area check out on 2024-09-12 21:16 and received by SSD on 2024-09-13 08:25 for operation on 13/9/2024 pm.

Characters Left 787

Recommendation The concerned staff should be alerted the case. Designated loading configuration with slope was recommended to lower the chance of water droplet.

Characters Left 854

Follow Up(1000) Concerned staff was interviewed. To share the case on 20/09/2024 weekly training.

Characters Left 918

Staff Involve ☐ Uncertain Staff **Staff Role**


PCA II	Packer
C II	Checker

Photos

Add File **Save As**

Files

3) Multidisciplinary approach



4) Engagement of Frontline Staff




Test performed in CSSD Tuen Mun Hospital

- 1 gallipot of sterile water (less than 50 ml) were randomly poured on to the instrument to simulate an **extreme situation / the worst case**.
- The tested item sets were undergone normal steam sterilization cycle





➤ Before Sterilization



IMPLANT SYSTEM



➤ After Sterilization





Thank you for your attention

26TH WORLD STERILIZATION CONGRESS

BRING THE STERILIZATION SCIENCE TO THE NEXT LEVEL
將滅菌科學提升到新水平

Supported by:
 HONG KONG TOURISM BOARD
香港旅遊發展局

 政府資助
Government Grants Programme

3RD TO 6TH
DECEMBER
2025

HONG KONG
ASIAWORLD-EXPO
亞洲國際博覽館