Lesson Learned from Decontamination Incidents - Challenging Design of Instruments



Health Facilities Scotland

Dr. Sulisti Holmes
Head of Decontamination & Incident
Reporting Investigation Centre





Why?

How?

What've we learned?

My questions to you?



WHY?

Orthopaedic

- 15 patients infected
- 78 years old female died

2009


Ophthalmic

- 5 patients endophthalmitis
- 75 years old female permanent visual deficit



Surgical site infections linked to contaminated surgical instruments

S.J. Dancer a, *, M. Stewart a, C. Coulombe a, A. Gregori b, M. Virdi c



HOW?



- 1. Quality Assurance Workshop
- 2. Reporting system
- 3.Investigations
- 4. Sharing & Collaborations

Retractor





An Example of Investigation




Investigation Timeline



FSN: Field Safety Notice

IFU: Instructions for Use





First Field Safety Notice 14 Jan 2013



All components –basket - WDManual cleaning

Surgical Instruments of Excellence Field

Field Safety Notice

Revised washing & cleaning Instructions

Super-Slide Laminectomy Retractor

Immediate Action Required

Date Issued; January 14th, 2013

Product; Super-Slide Laminectomy Retractor Set,

Code Numbers; 7329-00, 7329-05, 7329-05M, 7329-06 & 7329-99

Explanation; The purpose of this communication is to inform you of a risk of

inadequate decontamination with the Super-Slide Retractor Blades

and issue modified cleaning instructions.

We have found that if the Retractor Blades remain mounted in the Container supplied during the decontamination process there is the risk of contamination remaining in the area of the Retractor Blades which are in

contact with the Container.

Necessary Actions; In order to effectively decontaminate the Retractor remove all the

Retractor components from the sterilizing Container and place them into a standard wire basket. Manual washing of the Retractor Blades is

recommended to ensure effective decontamination of the Retractor.



Check on Another Site 22 Jan 2013











- Disregard previous IFU
- Use the new validated IFU

Surgical Instruments of Excellenc

Field Safety Notice

Revised washing & cleaning Instructions

Super-Slide Laminectomy Retractor

Immediate Action Required

Ref; FSCA 27.02.2013

Date Issued; February 27th, 2013

Product: Super-Slide Laminectomy Retractor Set,

Code Numbers: 7329-00, 7329-05, 7329-05M, 7329-06 & 7329-99


Explanation; This is a revision to our previous released FSN relating to our Super-Slide

II Retractor, we are now able to issue clinically validated cleaning &

sterilizing Instructions.


Necessary Actions; Disregard the previously issued instructions and use the validated

Cleaning & Washing Instructions provided with this notice.





Revised IFU – Feb 2013



Pre Cleaning: Retractor head - move back and forth along the full length of the rack, wipe the rack with cloth each time (x 3)

Service: Every 12 months or 300 uses





Inspection 8 Oct 2013


13 uses after services
IFU (Jan 2013)
Contaminants detected



Residual Protein Test Results







ProReveal

Clean Trace

Product Recall Third Field Safety Notice 10 Oct 2013



Cannot guarantee the removal of contamination when IFU is followed

Urgent Field Safety Notice

Mercian Super Slide Laminectomy Retractor System FSCA 10/10/13

Action to reduce risk of serious deterioration in state of health.

Date: 10/10/13

Attention: Owners and users of Mercian Super Slide Laminectomy Retractor System

Details on affected devices:

Mercian Super Slide Laminectomy Retractor System – part number refs 7329-00, 7329-05, 7329-05M, 7329-06, 7329-09, 7329-99

Description of the problem:

Mercian Super Slide Laminectomy Retractor System Cleaning and Sterilising Instructions cannot quarantee complete removal of contaminants from instrument when instructions are followed.

Potential hazard regarding contaminants remaining on instrument between head plates on retractor head.


Potential risk of transfer of contaminants between patients.

Previous use of affected devices may potentially have transferred contaminants between patients.

Advise on action to be taken by the user:

Mercian Surgical Supply Company Limited are unable to supply Cleaning and Sterilising Instructions which are guaranteed to completely remove contaminants from area between head plates on the retractor head. Because of this, we have determined that the device does not meet the Essential Requirements of 93/42/EEC and we are recalling the device. Please return the devices to Mercian Surgical Supply Company Ltd for the attention of the contacts given below.

Please do not use the device, and follow usual procedures for monitoring and recording postoperative infection in patients on whom the device has been used.







Patients left in limbo by recall of equipment used in back surgery

Five health boards have been affected after the manufacturers withdrew a device because of concerns about sterilisation.





Fourth Field Safety Notice 4 Nov 2013



- New validated IFU with dismantling & reassembly
- Resume clinical use
- No need to return device to supplier

Urgent Field Safety Notice

Mercian Super Slide Laminectomy Retractor FSN 08/11/13

Action to reduce risk of serious deterioration in state of health.

Date:08/11/13

Attention: Owners and users of the Mercian Super Slide Laminectomy Retractor System

Details on affected devices:

Mercian Super Slide Laminectomy Retractor System – Model numbers 7329-00, 7329-05, 7329-09, 7329-10, 7329-05M, 7329-06 and 7329-99

Description of the problem:

We have previously advised that our cleaning and sterilising instructions could not guarantee the complete removal of contaminants from the instrument, that there was a potential hazard of contaminants remaining between the plates on the retractor head and a potential risk of transfer of contaminants between patients.

We now have new instructions for cleaning and sterilising the retractor, with instructions for the dismantling and reassembly of the retractor frame. These allow the frame head to be effectively decontaminated and remove the hazards referred to on our previous communication. The efficacy of the new cleaning and sterilising instructions has been validated by laboratory testing.

Advice on action to be taken by the user:


Please follow the new cleaning and sterilising instructions supplied with this notice. Using these instructions, you can now resume clinical use of the device and there is no longer a requirement for the device to be returned to us.

Revised IFU - Nov 2013



- Fully dismantle the head unit of the Retractor Frame;
 - See appendix 1 for detailed instructions on dismantling the Retractor head.

Use slotted screw drivers








The Trial Reassembly 7 minutes












Findings: Damage and Fragmentation of Components

Redesigned Prototype Jan 2014



Redesigned Frame

- 2 Screws
- No more tool
- Spring a part of the lever







18 Nov 2014

Majority of UK devices were converted.






What've We Learned?



- 1. Can't fully dismantle? Risky!
- 2. Risk assessment
- 3. Validation
- 4. Clinical trial
- 5. Maintenance/service programme
- 6. Communication & Collaboration





My Questions to you?